


FRESE PIANE PER CONTORNARE CON LEVASPIGOLI A 45°/RAGGIO



- JOINTING CUTTERHEADS WITH CORNER REMOVERS AT 45° OR RADIUS
- PORTE-OUTILS A RABOTER ET DRESSER AVEC SUPPRIMEANGLES À 45° OU RADIES
- FUGE-MESSERKOPFE MIT ENTKANTERN ZU 45° ODER RADIAL
- FRESA CORTE RECTO PAR CONTORNEAR CON ACHAFLANADORES A 45° O CON RADIO

TC.03

Ø	n.min.	n.max.
140		8800
155		8400



Articolo	D	D.min	B	d	Z	↶	↷	Prezzo
TC. 03.01	140	125	55	30/35/40	2	SX	DX	M 33
TC. 03.02	155	140	55	30/35/40/50	2	SX	DX	M 34

RICAMBI-SPARE PARTS-RECHANGES-ERSATZTEILE-RECAMBIOS

Articolo	Descrizione	Dimensione	Prezzo
S0. CF.50	Coltello / Knife	50x12x1.5	B10
CU. TB.10	Cuneo / Wedge	50x12x10	A1
VU. DS.03	Vite / Screw	M8x22	A45
VU. OC.02	Ogiva / Nut	M8	A46
CU. 04110PD01	Cuneo / Wedge	20x25x10 DX	H9
CU. 04110PS01	Cuneo / Wedge	20x25x10 SX	H9
VU. DS.03	Vite / Screw	M8x22	A45
VU. OP.01	Ogiva / Nut	M8	A47
SC. CM.03	Chiave / Allen Key	B 4	A27

L'utensile viene fornito completo di una serie di coltelli per il raggio richiesto. (R= 2 - 3 - 4 - 5 - 6)


The tool is supplied complete with a set of knives for cutting the radius required. (R= 2 - 3 - 4 - 5 - 6)

Le port-outils vient livrer complete avec en jru de plaquettes pour le rayon demandé. (R= 2 - 3 - 4 - 5 - 6)

Das Werkzeug wird mit den Messern der gewünschten Radien geliefert (R= 2 - 3 - 4 - 5 - 6).

La herramienta se suministra con una serie de cuchillas para el radio deseadado. (R= 2 - 3 - 4 - 5 - 6)


- Esempi di lavorazione.
- Examples of processing.
- Exemples d'usages.
- Anwendungs-beispiele.
- Ejemplo de trabajos.



S6. 04110PD01
List. F29




S6. 04111PD01
List. F29




S6. 04112PD01
List. F29



S6. 04113PD01
List. F29



S6. 04114PD01
List. F29



S6. 04115PD01
List. F29

